

Jabra LINK 14201-33

FIRMWARE UPGRADE GUIDE

WWW.JABRA.COM

FIRMWARE UPGRADE GUIDE

Requirements:

- Windows PC
- Jabra PC Suite (download the latest version at jabra.com/pcsuite).

Follow these steps to upgrade the Jabra LINK 14201-33 firmware:

1 Disconnect the Jabra LINK 14201-33 from the headset and the desk phone.



2 Pull out the rubber plug from the Jabra LINK 14201-33, as illustrated.



3 Connect a standard micro USB cable to the Jabra LINK 14201-33 and the PC*.



* A micro USB cable can be purchased from Jabra as an accessory (#14201-26). The Jabra PRO 9400 Series and Jabra GO 6470 are supplied with a micro USB cable.

4 Start Jabra Control Center, and click Help > Check for updates. A list of connected Jabra devices will appear.



5 If an update is available for the Jabra LINK 14201-33, click Update.

labra Control Centi					- 1
	Help				
	Jabra LINK 33				
eck for Updates					
Product	Current Version	Latest Version	Release Date	Release Note	Status
labra PC Suite	2.8.1678.0	2.8.1611.0	2012-03-01	View	Up-to-date
labra LINK 33	1.1.0	1.2.0	2012-03-22	View	Update
/iteless devices must be lick Update button to up		oart on the PC, in	n order to be ch	ecked	Close
			OK	Cancel	Apply

6 Jabra Firmware Update screen will open. Follow the onscreen instructions to download the firmware update.





Firmware Update Wizard -	step 5 of 5	
	Writing flash	

f

7 When the update is complete, click finish.



8 Reconnect the Jabra LINK 14201-33 to your device/phone.



NOTE: If the micro USB cable from the Jabra PRO 9400 Series or Jabra GO 6470 was used, remember to reconnect it after updating Jabra LINK 14201-33.